

Hectic start debugging Parkes issues

- 1) atsnap didn't want to slew while the slew time was too long, had to manually slew the dish
close and then restart the schedule. There was another episode of this later on, so
we reverted atsnap to an earlier version
- 2) Wrong recorder was setup initially, it took a while to realise.

From:

<https://www.atnf.csiro.au/people/atzioumi/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/people/atzioumi/vlbi/dokuwiki/doku.php/lbaops/lbajul2018/v560apalog> 

Last update: **2018/09/11 12:18**