

CA06 had cryo maintenance and didn't participate. CA03 was excluded from the tied array beam early on (before the science part) at 05:35 UT due to rapid phase drifts (LO issues suspected). There were a few windstows early in the run.

According to RtFC, there was a likely delay jump at ATCA after the initial fringe finders and before 06:52 UT.

CA05 phases diverged significantly between auto-phasing done at 12:42 and 13:45 UT.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajul2021/v560hatlog?rev=1626657583>

Last update: **2021/07/19 11:19**

