

N.B.: No fringes found and later discovered 100 MHz LO reference not connected! Data not useful.

Ak setup to 8441 MHz centre frequency to match other antennas (NOT at 8425 as the wiki setup says).

Data recorded on /mnt/raid_1.

RMS levels 1670,1860. Clock diff ~1ms.ie. all appears normal. BUT no fringe was found with rtfc.

H-maser appears ok. re-sync'ed before run at about 8UT.

Antenna not tracking approx 22:00-23:47 UTC

Drives died again at 07:19 - recovered ~ 07:35

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajun2013/v252akaklog>

Last update: **2015/12/18 16:38**

