

Recorded using DBBC/mk5ho

Only one polarization channel on the Hobart 22 GHz system working at the moment (RCP label).
Hobart pointing checked and updated prior to the sessions, but still poor for 22 GHz work.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajun2017/v547cholog>

Last update: **2017/06/15 09:09**

