

Polarisations were opposite way than asked, when compared with ATCA. Swapped cables at 11:18UT.

To get correct bands needed to use profile aa4s_f.pro (flipped), opposite filp to wiki definition.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamar2007/vt02ipalog>

Last update: **2015/12/18 16:38**

