

Parkes has has poor polarisation sometimes and better others. As it is not consistently bad it is probably a setup related issue. Can this be checked carefully?

Recording on SWIN V004B at Parkes.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamar2008/vx014apalog>

Last update: **2015/12/18 16:38**

