

Antenna control crapped out around 07:15 UTC. Restarted at 07:30

Drive problem again around 07:45

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamar2013/v252aiaklog>

Last update: **2015/12/18 16:38**

