

Agilent 6.2 GHz

SML01/02 720 MHz

DAS profile 16\_ul\_n.pro

Fringes found.

Recording to CURT V004B.

Drive PC crashed on last scan at 17:24:27.

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamar2014/rk01vycdlog>

Last update: **2015/12/18 16:38**

