

Recording DAS1 to CURT V002B.

DAS AGC is turned off and noise diode disabled. Signal level into the DAS is not sufficient to get perfect statistics in this mode.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamar2014/rk02aymplog>

Last update: **2015/12/18 16:38**

