

Swapped pols

Missed scan 01:40-01:50 (and maybe before) due to control software failure

Missed many scans for the next hour then recorder seized up entirely. We could not recover.

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamar2015/v252ataklog>

Last update: **2015/12/18 16:38**

