2020/06/26 10:38 1/1

Some issues with one of the Parkes polarizations. During times when Parkes is not participating the receiver was switched off to "rest" the amplifiers and help

Times when the receiver was rested:

10:15 - 10:40 UT

14:00 - 14:45 UT

18:03 - 18:39 UT

18:45 - 20:10 UT (Parkes not scheduled for observing.)

22:55 - 23:20

From:

https://www.atnf.csiro.au/vlbi/dokuwiki/ - ATNF VLBI Wiki

Permanent link:

https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamar2015/v255xpalog

Last update: 2015/12/18 16:38

