

Initially recorded to UTAS V002A but recording stopped at 1807 to switch to /data/internal/ 1828 stopped and restarted recording (staying on /data/internal) as duration in cDisko was not long enough

Recording RCP, LCP (confirmed with fringe-check).

Agilent at 16.6 GHz

Second LO set to 636

Coherence with tone of 929.375 MHz

DAS profile VSOP_HO3.PRO

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamay2010/v253aholog>



Last update: **2015/12/18 16:38**