

Recording to ATNF V016B

CLKOFF not working - fmout-gps = 15.9 us

Agilent set to 14 GHz

SML set to 777 MHz

Recording RCP/LCP (confirmed with fringe check)

DAS profile VSOP.PRO

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamay2011/v448bholog>

Last update: **2015/12/18 16:38**

