

12:00:00 on point, recoding data to SWIN-V003A1-7

13:50:00-14:10:00 Not on point during pointing check It was discovered that pointing had been up to 35 millie degree off for unkown reason

14:10:59 Started on point with pointing corrected

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbanov2008/v252jtilog?rev=1227973243>

Last update: **2015/12/18 16:38**

