

Recording to CURT V006B

Recording RCP, LCP (confirmed with fringe-check)

Agilent set to 6.901 GHz

Second LOs are SMY01/SMY03 = 619 MHz

Coherence seen with a tone of 227.3 MHz.

System temperature measurements are not working reliably due to interference from the wireless data link. The Tsys should be ~500-600 Jy.

cDisko clock is 1m 40s fast.

Bigbuf error 13:07:32. Recording continuing okay.

Bigbuf error 13:34:39. Recording continuing okay.

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbanov2010/v293bcdlog>

Last update: **2015/12/18 16:38**

