

Note that band has been inverted with -invert option.

Fringes at start ok.

Generator servicing confusion around 07-07:30UT. Antenna may have gone down then?

~08:40UT Gui found frozen and tracking stopped. Restarted everything. Drives were off. (but recording ok)

08:53 Back onsource and recording.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbanov2012/v464aaklog>



Last update: **2015/12/18 16:38**