

Recording to PKS+0012

Mode is ext:0x00000f0f:1 (dbbc01/02 = RCP, dbbc05/06 = LCP)

ifa=1,agc,1,35000

ifb=1,agc,1,20000

tsysS ⇒ XRCP

tsysX ⇒ XLCP

Configuration confirmed by fringecheck

XLCP sensitivity lower than expected = DBBC/Como? issue as seen in IVS experiments.

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbanov2012/v471byglog>

Last update: **2015/12/18 16:38**

