

DAS Profile : VSOP.PRO (with inverted sidebands)

Agilent : 17.47 GHz

SML : 495 MHz maser mode ; 206/706 MHz ICRF mode

Not onsource after initial Maser mode 1921-293 scan (08:00 - 08:05) until 09:47 UT

Antenna problems from ~16:08 UT through to ~20:07 UT. It doesn't look like Ceduna was on source during that period.

The recorder stopped 10 minutes before the end of observation, but the last 5 minutes should have been recorded.

Data recored to CURT V006B

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbanov2013/v490bcdlog>

Last update: **2015/12/18 16:38**

