

Recording RCP/LCP

Agilent 16.6 GHz

SMLs 706 MHz

DAS: VSOP\_HO.PRO

Coherence seen with tone of 889.4 MHz

Recording to ATNF V016B

Windstowed 2145→0003

Windstowed 0014→0527

Windstowed 0543→0645

formatter-GPS counter was malfunctioning throughout this experiment and recorded a value of 0.99s. The correct maser-GPS offset is ~4.8 microseconds

From:

<https://www.atnf.csiro.au/people/atzioumi/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/people/atzioumi/vlbi/dokuwiki/doku.php/lbaops/lbanov2013/v498bholog>

Last update: **2015/12/18 16:38**

