

Recording DAS1 to the Xcube at ATCA.

DAS profile is 64MHz_n.pro, and inverted recording is off.

Fringes were obtained with ATCA in this configuration.

The recorder failed between 22:40 and 22:41, but I noticed right away and fixed it. Recording resumed at 22:44 UTC.

Recorder failed again between 04:05 and 04:06, and fixed it to resume recording at 04:10 UTC.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbaoct2015/v463hmplog>

Last update: **2015/12/18 16:38**

