

ATCA is in the 750A array, phase stability is not great. Auto-phasing doesn't seem to spoil the phasing of the array, but doesn't help much either.

From:
<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:
<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbaoct2018/rg39batlog>

Last update: **2018/10/28 11:06**

