

Tied antennas 12345

Recording stopped before end at 19:28:17. Restarted at 19:28:35.

Noticed recorder sampler stats on channel 1 (of 0-3) appear to fluctuate (between ~15-17%).

No other known problems.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbasep2015/v252axatlog>



Last update: **2015/12/18 16:38**